

Communications Sector Service Note

Non-Repairable Product List for Amateur Radio

Kenwood Amateur Radio products have been a success since their introduction in the early 1970's. Incredibly some of these very first products are still being used today.

Due to changes in technology and lack of sources for vintage parts, JVCKENWOOD USA can no longer support the repair of the models listed below. This policy will eliminate repeat repairs due to multiple failures because of product age.

KASC-Pacific or any Authorized Amateur Dealer is no longer authorized by Kenwood to repair the models below. Therefore Kenwood is not liable for the cost of any attempted repair or any shipping charges to and from the service center for these models listed below.

AT-120	RC-10	TH-77A	TM-421	TR-2600	TS-140 /S	TS-930
AT-130	RC-20	TH-78A	TM-431	TR-3200	TS-180	TS-940
AT-180	RZ-1	TH-79A	TM-451A	TR-3400	TS-430	TS-950S/SD/SDX
AT-200	SM-220	TKM-107	TM-455	TR-3500	TS-440	TV-506
AT-230	SM-230	TKM-207	TM-521	TR-3600	TS-450 /S	TV-520
AT-250	SW-2000	TKM-307	TM-531	TR-50	TS-50	TW-4000
AT-300	SW-2100	TKM-407	TM-541A	TR-7200	TS-511	TW-4100
DFC-230	T-599	TKM-507	TM-621	TR-7400	TS-520 /S/SE	VB-2530
DG-5	TH-205	TL-922/A	TM-631	TR-7500	TS-530	VB-50
DSP-100	TH-21	TM-201	TM-641A	TR-751A	TS-60	VC-10
HC-10	TH-215	TM-211	TM-642A	TR-7600 /25	TS-600	VC-20
IF-232C	TH-22AT	TM-221	TM-701	TR-7730	TS-660	VFO-120
MC-50	TH-25	TM-231	TM-721	TR-7800 /25	TS-670	VFO-180
MC-80	TH-26	TM-241A	TM-731	TR-7930 /50	TS-680 /S	VFO-230
MC-85	TH-28	TM-251A	TM-732A	TR-8200	TS-690 /S	VFO-240
PC-1 /1A	TH-31	TM-2530	TM-733A	TR-8300	TS-700	VFO-520
R-1000	TH-315	TM-255	TM-741A	TR-8400	TS-711	VFO-700
R-11	TH-41	TM-2550	TM-742A	TR-851A	TS-780	VFO-820
R-2000	TH-415	TM-2570	TM-941A	TR-9000	TS-790A	VFO-900
R-300	TH-45	TM-321	TM-942A	TR-9130	TS-811	
R-5000	TH-46	TM-331	TR-2200	TR-9300	TS-820 /S	
R-599	TH-48	TM-3530	TR-2300	TR-9500	TS-830	
R-600	TH-55	TM-401	TR-2400	TS-120	TS-850 /S/SAT	
R-820	TH-75	TM-411	TR-2500	TS-130	TS-900	

Any Kenwood models not listed here can still be repaired at the Kenwood National Service Center (KASC-Pacific).

Questions regarding service of Kenwood Amateur Radio products should be directed to the following:

KASC-Pacific, FTH Group

20801 Currier Road
 City of Industry, CA 91789
 Phone: 626-333-2443 voice prompt 9

Or Kenwood Amateur Customer Care at (310) 639-4200 voice prompts 4,1

WSR Service Code – Information Only
 Copyright © 2018 All Rights Reserved.

JVCKENWOOD USA Corporation
 PO Box 22745
 Long Beach, CA 90801
 Tel 310-639-4200